

## Release Notes

**Product Name:** EXT3-21-XR-TR

**Current Version:**

Type	Number	Date
Firmware	1.4.64565	October 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 25, 2023

**Reference:**

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
EXT3-21-XR-TR	N/A	N/A	N/A

### Summary:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### Replaced Products:

Product Name	Comments



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** EXT3-21-XR-TR

**Current Version:**

Type	Number	Date
Firmware	1.4.64565	October 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 25, 2023

**Reference:**

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/EXT3-21-XR-TR](http://www.kramerav.com/manual/EXT3-21-XR-TR)

### Issues to Fix in Future Versions:

ID	Deferred Issue Description
85402	Remote button volume up/down faulty operation.
85394	Time location isn't disabled for disabled NTP server.
85386	No pop-up message on invalid 802.1x credentials input.
85383	Incorrect P3K time query response.
84931,84929	CEC commands sending is enabled on Tx and active Rx HDBT input only.
84530	During PoE-powered Rx power-up, unclear sound may be heard on audio output.
84200	No command name edit when contains 2 spaces.
83735	Output Force HDCP is not supported.
82905	On DTS/DOLBY extraction, noise may be heard on audio output port.

### Known Limitations (including compatibility limitations):

ID	Limitation Description
85355	Tx: On no source connection, HDMI loop web-UI indication is OFF.
84532	Post reset Rx outputs initially HDBT input, then reverts back to output the previously-selected input signal.
84531	No audio output when display is unconnected.
84233	Input HDCP 2.2 signal is not displayed on HDCP 1.4 display.
84220	Occasionally, fail to detect output TV HDCP support.
82958	Using as 2x1 Rx, longer (then standard) ~4-5sec HDMI & HDBT switching time may occur.



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

Preceding Version: N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)