

Release Notes

Product Name: DSP-62-UC

Current Version:

Type	Number	Date
Firmware	1.0.60809	September 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 12, 2021

Reference: 08466

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
DSP-62-UC	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.

Codependency with Other Products and Software:

- There is no codependency with other products or software.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: DSP-62-UC

Current Version:

Type	Number	Date
Firmware	1.0.60809	September 2021
Software	–	–
Web	–	–
Hardware	–	–

RN Date: September 12, 2021

Reference: 08466

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/DSP-62-UC

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
19431	#GPIO-STATE? Protocol 3000 API command: Value of 1 always returns an error.

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
19030	Firmware Upgrade: We recommend upgrading firmware over a network/Ethernet connection. If the network is not available, firmware can be upgraded using K-Upload over the RS-232 serial connection. In that case, please disconnect the device from the network before performing firmware upgrade.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com