

## Release Notes

**Product Name:** SWT3-41-U-T

**Current Version:**

Type	Number	Date
Firmware	V1.0.64879	November 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 30, 2023

**Reference:**

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-41-U-T	N/A	N/A	N/A

### Summary:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### Replaced Products:

- N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** SWT3-41-U-T

**Current Version:**

Type	Number	Date
Firmware	V1.0.64879	November 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** November 30, 2023

**Reference:**

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/SWT3-41-U-T](http://www.kramerav.com/manual/SWT3-41-U-T)

### Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
1838	Control gateway is supported for TCP clients only.
	Detected buttons click is longer than standard.
	Rarely, especially post power-cycle, plugged USB-C source is undetected. Workaround: Unplug & re-plug source.

**Known Limitations (including compatibility limitations):** N/A

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)