

## Release Notes

**Product Name:** SWT3-41-U

**Current Version:**

Type	Number	Date
Firmware	V1.0.64471	October 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 25, 2023

**Reference:**

### Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
SWT3-41-U	N/A	N/A	N/A

### Summary:

- This is a release note for a new product.

### Codependency with Other Products and Software:

- There is no codependency with other products or software.

### Replaced Products:

Product Name	Comments



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)

## Release Notes

**Product Name:** SWT3-41-U

**Current Version:**

Type	Number	Date
Firmware	V1.0.64471	October 2023
Software	–	–
Web	–	–
Hardware	–	–

**RN Date:** October 25, 2023

**Reference:**

This is a release note for a new product. For a list of new product features see:

[www.kramerav.com/manual/SWT3-41-U](http://www.kramerav.com/manual/SWT3-41-U)

### Issues to Fix in Future Versions:

ID	Deferred Issue Description
85394	Time location isn't disabled for disabled NTP server.
85264	Following FW upgrade, priority switching is activated only after a 2nd reset.
84200	No command name edit when contains 2 spaces.

### Known Limitations (including compatibility limitations):

N/A

**Preceding Version:** N/A



**KRAMER ELECTRONICS, Ltd.**

E-mail: [info@kramerav.com](mailto:info@kramerav.com)

Web: [www.kramerav.com](http://www.kramerav.com)