

Release Notes

Product Name: WP-871xr

Current Version:

Ver.Type	Ver No.	Date
Firmware	EP91C1E_NON_171201	August 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 2018

Reference: 12703

Kramer Product Affected:

Product Name	Minimum FW Version for Upgrade	Recommended for All Units	Only if Added Features are Required
WP-871xr	N/A	N/A	N/A

Technical Notes:

- This is a release note for a new product.
- Limitation: Source and display AV signal compatibility must adhere to EDID parameters. Incompatibility may cause signal delivery failures, such as audio noise payout.

Codependency with Other Products and Software:

Product Name	Comments
PT-872xr	Compatible receiver.



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com

Release Notes

Product Name: WP-871xr

Current Version:

Ver.Type	Ver No.	Date
Firmware	EP91C1E_NON_171201	August 2018
Software	–	–
Web	–	–
Hardware	–	–

RN Date: August 2018

Reference: 12703

This is a release note for a new product. For a list of new product features see:

www.kramerav.com/manual/WP-871xr

Bugs to Fix in Future Versions:

QC ID	Deferred Bug Description
	None listed

Known Limitations (including compatibility limitations):

QC ID	Limitation Description
	For specified extension distance performance, use Kramer DGKat cables with no mid-span cable connections.
	Use only shielded cable with both ends of the shield soldered to ground to eliminate ESD interface and with no mid-span cable connections.

Preceding Version: N/A



KRAMER ELECTRONICS, Ltd.

E-mail: info@kramerav.com

Web: www.kramerav.com